From: <u>Sanchez, Carlos</u>

To: Leos, Valmichael; Miller, Garyg; Foster, Anne; Walters, Donn

Cc: Meyer, John

Subject: RE: San Jacinto River Waste Pits cap inspection report 06/15/15

Date: Wednesday, June 17, 2015 9:19:44 AM

Val,

Based on the inspection and the finding, we do not believe that an emergency repair is warranted at this time

We understand that repairs are needed. That is why you should wait for the managers to review the report before it is sent out. CAS

Carlos A. Sanchez
Chief, Superfund AR/TX Section
214-665-8507
Sanchez.carlos@epa.gov

From: Leos, Valmichael

Sent: Wednesday, June 17, 2015 9:11 AM

To: Sanchez, Carlos; Miller, Garyg; Foster, Anne; Walters, Donn

Cc: Meyer, John

Subject: RE: San Jacinto River Waste Pits cap inspection report 06/15/15

Gary reviewed and had no comments. You were not in office yesterday.

Sincerely,

Valmichael Leos

Remedial Project Manager

U.S. Environmental Protection Agency Region 6

0: 214-665-2283

E: leos.valmichael@epa.gov

From: Sanchez, Carlos

Sent: Wednesday, June 17, 2015 8:06 AM

To: Leos, Valmichael; Miller, Garyg; Foster, Anne; Walters, Donn

Cc: Meyer, John

Subject: RE: San Jacinto River Waste Pits cap inspection report 06/15/15

Val,

We want to review and comment on the inspection report before it is sent out to anyone. Thanks CAS



Carlos A. Sanchez Chief, Superfund AR/TX Section 214-665-8507 Sanchez.carlos@epa.gov

From: Leos, Valmichael

Sent: Tuesday, June 16, 2015 4:01 PM

To: Miller, Garyg; Sanchez, Carlos; Foster, Anne; Walters, Donn

Cc: Meyer, John

Subject: San Jacinto River Waste Pits cap inspection report 06/15/15

All,

Please find attached the latest cap inspection report for the San Jacinto River Waste Pits superfund site.

Sincerely,

Valmichael Leos Remedial Project Manager U.S. Environmental Protection Agency Region 6

O: 214-665-2283

E: leos.valmichael@epa.gov